

Annexure D

BUILDING SAFETY CERTIFICATE

No. _____

Dated: _____

It is certified that the existing building SGS International School (name of the building or premises) at Ramnagar, South Ramnagar, Barnulpur - 743987 (address) is having block(s)/Floor(s) as per details below:

Detail of Block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block	Ground + 3 Floor					

The building is owned/occupied by SGS International School, Ramnagar (name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of _____ (Name of Department/ Govt.) on _____ (date of inspection) in the presence of Deepti Mukherjee Patra (Principal) (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from 05/11/2024 for a period of 1 (one) yr years in accordance with rule and subject to compliance of the specific conditions as appended.

- 1.
- 2.
- 3.
- 4.

Issued on 05/11/2024 at 04/10/2025 by _____

* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.

Signature with Seal: _____

Name: GAUTAM DAS

Designation: _____

Name & Address of Department/ Office: _____

05/11/24
District Engineer
South 24 Pargana Zilla Parishad